



Date: Monday, 20/10/2008 3:28:05 PM
 User: Julie Dawson

Process Sheet

Customer : CU-DAR001 Dart Helicopters Services	Drawing Name : OVERHEAD , RH
Job Number : 42741	
Estimate Number : 13615	
P.O. Number :	Part Number : D38312
This Issue : 20/10/2008 S.O. No. :	Drawing Number : D38312 PROTOTY[E
Prsht Rev. : NC	Project Number : IN0002
First Issue : / / Type : R&D THERMOFORMING	Drawing Revision : PROTOTYPE
Previous Run : 42395	Material : KYDEX 6185 (TBD)
Written By : 	Due Date : 27/10/2008 Qty: 1 Um: Each
Checked & Approved By : 	
Comment : EST. Rev. A New Issue 08/09/25 DL	

Additional Product

FOR ENGINEERING USE ONLY

PROTOTYPE

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	HAND FINISH TH	HAND FINISHING THERMOFORMING
-----	----------------	------------------------------



Comment: HAND FINISHING THERMOFORMING

1) Machine set up

DL 08.10.21

2.0	HAND FINISH TH	HAND FINISHING THERMOFORMING
-----	----------------	------------------------------



Comment: HAND FINISHING THERMOFORMING

1) Cut sheet to required blank size

DL 08.10.21

3.0	THERMOFORMING	THERMOFORMING MACHINE
-----	---------------	-----------------------



Comment: THERMOFORMING MACHINE

Thermoform as per Dwg. D3831-2 and folio (FTA 9344Prototype) using tool DT 9344

Dwg. Rev. PROTOTYPEFolio Rev. A

DL 08.10.21

4.0	QC2	INSPECT PARTS AS THEY COME OFF MACHINE
-----	-----	--



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

Visually inspect for proper formation of each part

DL 08.10.21

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Monday, 20/10/2008 3:28:05 PM
User: Julie Dawson

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: OVERHEAD , RH

Job Number: 42741

Part Number: D38312

Job Number:



Seq. #: Machine Or Operation: Description :

5.0

QC8

SECOND CHECK



BB1 08/10/21 (X1)



Comment: SECOND CHECK

6.0

HAND FINISH TH

HAND FINISHING THERMOFORMING



Comment: HAND FINISHING THERMOFORMING

1) Trim to Finished Dimensions

Sl. 08.10.21 (X1)

7.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

Check dimensions to ensure conformity to drawing tolerances.

PROTOTYPE
KEEP IN
ENG'G LAB P/B 09.02.20

8.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

**ENGINEERING
APPROVAL**

9.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: _____

10.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



U 09.02.24

00251A

hooking mat'l
used per Dwyf

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries